





UNITOR HPC 61 HW

Instructions for use











A






B




B4.a




B4.b






B5



B6




B




C


C1.a




C1.b







C1.c






C




D




E




E4





E5





E6




E7





E8



E9





E10.a







E10.b



Max 100°C/210°F





E10.c




A


E11




E12






E12.b




E12.c




E13




F1



F2




F3




F

F4



F5



F6






F7



G



G1



G2


B

C




H1.a


A



B




C




H1.b

A




B




H2

A




B




H3

A



B



H4

