


Drop Test Method

LR Hardness (4 to 100mg/l CaCO_3)



1.

2.

3.

4.

1. Measure out 5mls of sample water.
2. Add 4 drops of TH Reagent 2 and mix.
3. Add 3 drops of TH Reagent 5 and mix.
4. Add drops of TH Reagent 3 with mixing until the pink colour turns to blue. Count the no. of drops.
5. Total Hardness = No. drops TH Reagent 3 x 4.
6. Record the result on log sheet and/or Waterproof.

LR Hardness Test Kit ref. 778114

